



Appendix C: Monitoring Data


Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-2 Total Phosphorus




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-3 Total Phosphorus




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-4 Total Phosphorus




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-5 Total Phosphorus



Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring BV SI-7 Total Phosphorus




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-9 Total Phosphorus




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-2 Nitrate and Total Ammonia Nitrogen

● Nitrate ● TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-3 Nitrate and TAN

● Nitrate ● TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-4 Nitrate and TAN

● Nitrate ● TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-5 Nitrate and TAN

● Nitrate ● TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-7 Nitrate and TAN

● Nitrate ● TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-9 Nitrate and TAN


● Nitrate ● TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-2 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-3 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-4 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-5 Chloride



Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-7 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-9 Chloride




Bayshore Village Effluent Spray Irrigation Wainman's Creek Water Quality Monitoring Total Phosphorus


● Upstream From Spray Irrigation Area ● Downstream From Spray Irrigation Area




Bayshore Village Effluent Spray Irrigation Soil Quality Monitoring
North Field Upper - Total Phosphorus




Bayshore Village Effluent Spray Irrigation Soil Quality Monitoring
North Field Lower - Total Phosphorus




Bayshore Village Effluent Spray Irrigation Soil Quality Monitoring
South Field - Total Phosphorus



Bayshore Village Effluent Spray Irrigation Soil Quality Monitoring
North Field Upper - Chloride



Bayshore Village Effluent Spray Irrigation Soil Quality Monitoring
North Field Lower - Chloride



Bayshore Village Effluent Spray Irrigation Soil Quality Monitoring
South Field - Chloride

